

Utah Department of Environmental Quality

Division of Drinking Water

Public Water System Inventory Report

Run Date:
08/04/2011 11:38 am

PWS ID: UTAH02071 **Name:** BEAVER DAM CHURCH
Legal Contact: CORP OF PRESIDING BISHOP- LDS CHL **Rating:** Approved
ROY BENSON MCDANIEL **Rating Date:** 11/14/2007
Address: 50 E NORTH TEMPLE ST, RM 1205 **Activity Status:** Active
SALT LAKE CITY, UT 84150-6320
Phone Number: 801-240-4656
City Served (Area):
County: BOX ELDER COUNTY
System Type: Non-community **Last Inv Update:** 08/10/2010 **Avg Daily Prod:**
Activity Status Cd: Active **Last Snty Srv Dt:** 04/18/2007 **Total Dsgn Cap:**
Population: 60 **Surveyor:** DAVID F HANSEN **Total Emerg Cap:**
Oper Period: 1/1 to 12/31

Gal/Day Gal/Min

Contacts

Contact Type	Name	Title	Phone Numbers		Email Address
			Office	Emergency	
AC	MCDANIEL, ROY BENSON	ENGINEER	801-240-4656	801-446-8498	mcdanielrb@ldschurch.org

Service Connections

Connection Type	Meter Type Code	Meter Size	Number Connections
Combined	Unknown	0	2
			2 Total Svc Connections

Distribution System

Pump Type	Total Dyn Head ft H2O	P.S.I.	Pressure Adequate	Cross Connection	Auhority Statement
No					

Sources

No.	Source Name	Activity Status	Source Type	Well Dia.	Safe Yield *	Pump Capacity	Location Data On File	Water Type	Availability	Period of Operation	Grnd Wtr Indicator
WS001	OLD CHURCH WELL	Inactive	WL				Yes	GW	Permanent		
WS002	97 CHURCH WELL	Active	WL		20 GPM	20 GPM	Yes	GW	Permanent	1/1 to 12/31	
WS003	DISALLOWED WELL	Inactive	WL				Yes	GW	Other		

*Reports measured flow for wells, approved design capacity for all other sources.